



The .gov means it's official.
Federal government websites often end in .gov or .mil. Before sharing sensitive information, make sure you're on a federal government site.



The site is secure.
The **https://** ensures that you are connecting to the official website and that any information you provide is encrypted and transmitted securely.



Occupational Safety and Health Administration

[CONTACT US](#) | [FAQ](#) | [A TO Z INDEX](#) | [LANGUAGES](#)

Menu

[OSHA](#) ▾ [STANDARDS](#) ▾ [ENFORCEMENT](#) ▾ [TOPICS](#) ▾ [HELP AND RESOURCES](#) ▾ [NEWS](#) ▾ [CONTACT US](#) [FAQ](#) [A TO Z INDEX](#) [LANGUAGES](#)

Inspection Detail

Inspection: 311637748 – Monte Carlo Resort & Casino

Inspection Information - Office: Nv-E-Las Vegas 0953220

Inspection Nr: 311637748

Report ID: 0953220

Date Opened: 01/25/2008

Site Address:

Monte Carlo Resort & Casino
3770 Las Vegas Blvd., South
Las Vegas, NV 89109

Union Status: Union

SIC:7011

NAICS: 721120/Casino Hotels

Mailing Address:

, , 00000

Inspection Type: Accident

Safety/Health: Safety

Scope: Partial

Close Conference: 05/02/2008

Advanced Notice: N

Planning Guide: Safety-Manufacturing

Ownership: Private

Emphasis: S:Hotel/Casino

Case Closed: 05/16/2008

Related Activity

Type	Activity Nr	Safety	Health
Accident	101044881		

Violation Summary

Violations/Penalties	Serious	Willful	Repeat	Other	Unclass	Total
Initial Violations				1		1
Current Violations				1		1

Initial Penalty	\$0	\$0	\$0	\$750	\$0	\$750
Current Penalty	\$0	\$0	\$0	\$750	\$0	\$750
FTA Penalty	\$0	\$0	\$0	\$0	\$0	\$0

Violation Items

#	Citation ID	Citation Type	Standard Cited	Issuance Date	Abatement Due Date	Current Penalty	Initial Penalty	FTA Penalty	Contest	Latest Event	Note
1.	01001	Other	618038301	05/07/2008	05/10/2008	\$750	\$750	\$0		-	

Investigation Summary

Investigation Nr: 201043627

Event: 01/25/2008

Employees get hospitalized from roof fire

On January 25, 2008 Employee #1 of Union Erectors, LLC., was performing hot work operations on an upper platform of the roof along with a team of co-workers. They were installing a platform davit system (catwalk) that would encompass the entire interior wall. While installing the catwalk, the employees were using a "saws all", an angle grinder and an oxygen-acetylene torch to reach and remove welds that had been left there from the previous installation. A fire started when sparks or slag from the hot work operations landed on the lower section of an adjacent wall igniting a blaze. The fire continued to travel to the exterior facade and to several upper floors of the resort and casino. Sufficient precautions were not taken to guard against a fire and several resort employees were transported to the hospital and treated for smoke inhalation after evacuation of the building was initiated. Employee #1 and #2 were hospitalized.

Keywords: BURN, ROOF, FIRE, TORCH, CATWALK

Investigated Inspection

#	Inspection	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	311637748			Hospitalized injury	Other	Occupation not reported
2	311637748			Hospitalized injury	Other	Occupation not reported

[OSHA](#) |
 [Standards](#) |
 [Enforcement](#) |
 [Topics](#) |
 [Media Center](#) |
 [Contact Us](#)



U.S. DEPARTMENT OF LABOR

Occupational Safety and Health
Administration
200 Constitution Ave NW
Washington, DC 20210
☎ 1-800-321-OSHA
1-800-321-6742
www.osha.gov

FEDERAL GOVERNMENT

[White House](#)

[Disaster Recovery Assistance](#)

DisasterAssistance.gov

USA.gov

[No Fear Act Data](#)

[U.S. Office of Special Counsel](#)

OCCUPATIONAL SAFETY & HEALTH

[Frequently Asked Questions](#)

[A - Z Index](#)

[Freedom of Information Act - OSHA](#)

[Read the OSHA Newsletter](#)

[Subscribe to the OSHA Newsletter](#)

[OSHA Publications](#)

[Office of Inspector General](#)

ABOUT THE SITE

[Freedom of Information Act](#)

[Disclaimers](#)

[Plug-Ins Used on DOL.gov](#)

[Accessibility Statement](#)

[Privacy & Security Statement](#)

[Important Website Notices](#)

[Site Map](#)

Connect With DOL

